

TE CONNECTIVITY PART NUMBER	PREVIOUS PART NUMBER	CABLE TYPE
1050717-1	2001-7141-00	Flexible Cable
1050718-1	2001-7141-02	
1050720-1	2001-7188-00	
1050721-1	2001-7188-02	
1050724-1	2001-7195-00	
1050900-1	2002-7141-00	
1050901-1	2002-7141-02	
1050903-1	2002-7188-02	
1049067-1	SDC, 2001-7195-00, SMA	

Figure 1

1. INTRODUCTION

This instruction sheet contains the assembly procedures for the SMA Straight Cable Connectors shown in Figure 1. These connectors are clamp attachment type connectors that attach to the cable type listed in Figure 1. Figure 1 also contains the previous SMA Straight Cable Connector part numbers.

NOTE *Dimensions on this sheet are in millimeters [with inches in brackets], unless otherwise specified. Figures are not drawn to scale.*

The table in Figure 2 references the tool required to apply this connector. The table includes tool description, TE part number, and the corresponding previous part number.

APPLICATION TOOLING		
Tool Description	TE Part No.	Previous Part No.
Center Contact Holder Assembly	1055454-1	2098-5221-10 (T-4578)

Figure 2

2. ASSEMBLY PROCEDURES

2.1. Preparing the Cable (Figure 3)

1. Place the clamp nut onto the cable.
2. Trim the cable jacket, cable braid, and inner conductor to the length shown in Figure 3.
3. Flare the cable braid.




Figure 3

Reasons for re-issue can be found in Section 4, REVISION SUMMARY.

2.2. Assembling the Collar Assembly (Figure 4)

1. Slide the collar assembly over the cable dielectric and under the cable braid and jacket (the center conductor should protrude through the collar assembly approximately 1.02 [.040]).
2. Trim and remove the excess cable braid strands.

2.3. Soldering the Center Contact to the Center Conductor (Figure 5)



To avoid personnel injury, be sure to follow all local and safety practices when using soldering equipment.

1. Tin the center conductor of the cable.
1. Place the center contact in the center contact holder (see Figure 2). Heat the center contact and push it over the center conductor of the cable so that it butts against the cable dielectric.

2.4. Securing Housing to the Clamp Nut (Figure 6)

1. Assemble the dielectric over the center contact.
2. Slide the clamp nut over the collar assembly and screw into the housing.
3. Torque to 25 inch-pounds.


3. INSPECTION

Adherence to the above steps should yield the tolerances shown in Figure 7.

4. REVISION SUMMARY

Since the previous version of this document, the following changes were made:

- Updated document to corporate requirements.



Note: Two Optional Slits (3.05 [0.12] Long) May be Cut in the Cable Jacket (1805 Apart) to Ease Assembly.

Figure 4




Figure 5




Figure 6




Figure 7