


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



	_	GmbH	HAND					tol	erance		scale: 4:1
	^ ⊃T 10U	نق									material: SEE SHEET 1
1 🛱	ED OR AY NOT WITHOU	WNERSHIP AND COPYRIGHT OF CONEC	O NOT ALTER CAD DRAWING BY							dim. in mm	
									date	name	title:
	ш∢Ф							drawn	23.09.14	Lehmenkühler	RECOMMENDED PANEL CUT-OUT
	⊥ A Β							appd.	26.01.15	Fischer	D-SUB FEMALE 25pos. SOLDER CUP
	NY NO NY V T A							norm			with closed 4-40 UNC thread
	G MA IN A N TO N TS							d-old			dwg no: DIN-
	WING CED I D ON PERM			1 x c	Ä5827	25.09.15	Unkrüer		45 =		15K1A1538
	DRA ODU ASSE			а	Original						15K1A1536 sh: 2
	HIS EPR EPA			rev.	description	date	name	7		71-6	part no: SEE SHEET 1