


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



	T	HAND					tol	erance		scale: 4:1
	ED OR AY NOT WITHOU	ַבֿן כַּ								material: SEE SHEET 1
	N L	G BY F							dim. in mm	
	H € ×	3 5						date	name	title:
T BE AY, A IRD P	AND AND PAR	DRAWING					drawn	29.09.14	Lehmenkühler	RECOMMENDED PANEL CUT-OUT
	IOT BI WAY, HIRD I.						appd.	26.01.15	Fischer	D-SUB FEMALE 25pos. SOLDER CUP
A TH.		A B					norm			with open 4-40 UNC thread
	¥ P P S S		dwg no: DIN-							
		A		Ä5827	25.09.15	Unkrüer		45 =		15K1A1544
	DRA ODU ASSE TEN	a Original Text A5827 25.09.15 Unkruer CONTROLL A ORIGINAL A		15K1A1544						
	HIS EPR SE PA			description	date	name	4		71-6	part no: SFF SHFFT 1