


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at $350 \,^{\circ}$ C, 50 Watt max. and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- 9. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



_															
	r DUT GmbH	HAND					tolerance			ϕ	scale:		3:1		
	ED OR AY NOT WITHOU ONEC G	B⊀								Ψ	material:	material: SEE SHEET 1			
DRAWING MAY NOT BE COPIED OR	IED OR MAY NO- Y WITHC								dim. ir	n mm					
	밝호는 유							date	name	е	title:				
	E COPIE AND M/ PARTY HT OF C	DRAWING					drawn	07.09.15	Hennel	boel	RECOM	RECOMMENDED PANEL CUT			OUT
	. ~~ ~						appd.	07.09.15	Lehmenk	kühler	D-SUB HD MALE 26pos. SOLDER (R CUF	•
	ANY V ANY V O A TH COPY	CAD					norm				with threaded insert and hexlocki dwg no:		ig scre	N	
	₹ A C SS C	띮					d-old								DIN-
	RAWING DUCED I SED ON IN PERM SHIP AN	AT.					_	45 =		4 0		1EV1 A1660			А3
	DRA ODU ASSE TEN ERSF	NOT	а	Original				()			15K1A1662			n: 2/2	
	THIS DE REPROD BE PASS WRITTE OWNERS	00	rev.	description	date	name	7	7/1	78-7		part no:	SEE SH	IEET 1		
			D		A .		-								