What's in the box

SPECS

AC/DC Voltage Measurement	**1mV to 600V DC, 600V AC (True RMS), CAT III, ±1%**
AC/DC Current Measurement	**1uA to 10A AC (True RMS)/DC max, ± 1%**
Resistance Measurement	**100m to 1M Ohm ±1%, 3M Ohm ±5%**
Ambient Temp. Measurement	**0 to 60ºC ±1ºC / 32 to 140ºF ±1.8ºF**
Continuity	✓
Capacitance	**1nF to 1000µF, ±2%**
Diode Check	**0V to 1V**
Sampling	**12-bit, 1Msample/s**
Digital Fourier Transformer (DFT)	✓
Logging	**28kB, 10min/sample @ 6 months**
Logged Parameters	**Voltage, Current, Temperature**
Bluetooth Range	**10mts / 30ft**
Operating Temp.	**-10 to 40ºC / 14 to 104ºF**
Battery	**Rechargeable (USB-C)**
EMC	**CE, FCC, RCM, MiC**
Lead span	**800mm, 31.5"**

Learn more **pokitinnovations.com**

hello@pokitmeter.com

pokitinnovations.com

pokit PRO

All-In-One Multimeter, Oscilloscope and Logger

Measurement, Unleashed.

Full-featured 600V, CATIII

Wireless Phone Connectivity

Compact and Portable

THE ULTIMATE TOOL FOR MAKERS, ELECTRONIC ENTHUSIASTS AND ENGINEERS

Transform your smart phone into an awesome tool

10A, 600V, CAT III

Multichannel Digital Storage Oscilloscope

Smart Watch App

Stand-alone Data Logger

Rechargeable Battery



Pokit Pro is an all-in-one multimeter, oscilloscope and logger with unprecedented portability, accuracy and versatility. Free yourself from the bench and take your creativity to new places!

Pokit Pro is ideal for electronics, automotive applications, home electrical, and much more.

APP FEATURES

Multimeter Mode

- DC Voltage
- AC Voltage RMS
- DC Current
- AC Current RMS
- Capacitance
- Resistance
- Continuity
- Diode Polarity
- Temperature
- Log Measurements

Oscilloscope Mode

- AC/DC Coupling
- AC/DC Current Signals
- Spectrum analyzer
- Continuous acquisition
- Triggers
- Cursors
- Scope measurement functions



Pinch drag and zoom, add cursors, measure deltas

Set triggers to: auto, rising or falling edge

Save and export measurements to csv file

Logger Mode

- DC Coupling
- AC Coupling
- DC Current Signals
- AC Current Signals
- Temperature Logging



Standalone logger

Pinch drag and zoom, add cursors, measure deltas

Save and export measurements to csv file