





KIT Visserie MOUNTING KITS

1LK00200




4 Vis tête pozidrive 2
CLZ M4 x 12 Ac. zingué


4 screws M4x12
POZIDRIVE 2




4 Rondelles contact
CS Ø 4 x 10 cadmiées
bichromaté
4 contact washer Ø 4 x 10



4 Appuis 12 x 8 x 2
Ø 4,3 Inox (plan 35.4.147)
4 rectangular washer
12x8x2mm




4 Ecrous QL M4
(carré de 8) Ac. zingué
4 square nuts M4



4 Vis tête pozidriv
CLZ M4 x 16 Ac.
zingué

4 screws M4x16
POZIDRIVE 2



4 Vis tête PHILIPS
M5 x 10 avec rondelle
imperdable

