

MT-1707 3-5/6 True-RMS Multimeter is designed for accurate measurements, ideal for a wide variety of electrical and electronic testing applications.

Positions. Full Functions 311

- Special design for ACV/ACA True-RMS measurement.
- Measuring DCV/ACV/DCA/ACA/resistance,capacitance/ Hz duty cycle/temperature/live wire test and diode.

V	٧~	A	A~	Ω	Hz	-11-	°C⁄F
Hz Duty	• 1))		X	HOLD	AP OFF	- +	

Non Contact Voltage Detector

tests AC 90-1000V

Voltage level indicator

To show the voltage signal intensity

Friendly Extra Functions

Continuity with beeper, duty cycle, data hold, auto power off,LED light, low battery indication and input alert protection ensures uninterrupted operation and long life.

Specifications	MT-1707				
DCV	600mV/6V/60V/600V/1000V ±(0.5%+3d)				
ACV TrueRMS	6V/60V ±(0.8%+3d) 600V/750V ±(1%+10d) Frequency Response : 40Hz-1KHz				
DCA	60uA/6mA/60mA/600mA±(0.8%+3d) 10.00A±(1.2%+3d)				
ACA TrueRMS	60mA/600mA±(1%+3d) 10.00A±(1.5%+3d) Frequency Response : 40Hz-1KHz				
Frequency (Hz)	9.999Hz/99.99Hz/999.9Hz/9.999KHz/ 99.99KHz/999.9KHz/9.99MHz ±(1.0%+3d)				
Resistance	600Ω/6kΩ/60kΩ/600kΩ/6MΩ±(0.8%+3d) 60MΩ±(1.2%+30d)				
Capacitance	6nF±(4.0%+30d) 60nF/600nF/6uF/60uF/600uF/6mF±(4.0%+3d) 100mF ±(5.0%+3d)				
Temperature	-20°C~1000°C/-4°F~1832°F±(1.0%+3d)				
Fuse	FF600mA/1000V, FF10A/1000V				
Power	4 x 1.5V AA Batteries (not included)				
Weight	340g (without battery)				
Dimension	192 (L)×89 (W)×55(H)mm / 7.5"x3.5"x2.5"				
Individual packing	Color Box				







LED light



I ive wire test



Non contact voltage detector





Phone: 804-561-2610 Fax: 804-561-2642 Web Site: www.eclipsetools.com

Picture for reference only. Please check with distributor for exact offers. All specifications are subject to change without notice



CE CATILI 1000V CATIV 600V