

PCE Americas Inc.
711 Commerce Way
Suite 8
Jupiter
FL-33458
USA
From outside US: +1
Tel: (561) 320-9162
Fax: (561) 320-9176
info@pce-americas.com

PCE Instruments UK Ltd.
Units 12/13
Southpoint Business Park
Ensign way
Hampshire / Southampton
United Kingdom, SO31 4RF
From outside UK: +44
Tel: (0) 2380 98703 0
Fax: (0) 2380 98703 9
info@pce-instruments.com

www.pce-instruments.com/english www.pce-instruments.com

Technical Gloss Meter PCE-IGM 100

Gloss meter for mobile use / different measuring geometries / 3.5 " TFT-Display / fast measurement time / internal data memory / including evaluation software

A gloss meter is a tester for determining surface gloss. Thereby, with the glossmeter, spectral reflections of a light beam that hits the surface, are measured. The touch screen allows for easy navigation.

The gloss meter is applied especially in areas where it is important that the surfaces have the same structure, and thus have the same surface characteristics. This often happens in quality control. Thus, the gloss meter is a measuring instrument whichcan be used in many different companies.

Included with this gloss meter there is also a CD-Rom with special evaluation software. So the measured data can be firststored on the device and later transferred to a computer. The software of the gloss meter also has an analysis function thatserves for precise evaluation.

- different measuring geometries
- 3.5 " TFT
- internal data memory
- calibration plate supplied
- fast measurement time
- with evaluation software

Technical Data

Measuring geometries 20 ° / 60 ° / 85 °/ 20 ° 60 ° 85 °

Display 3.5 " TFT touch display (320 x 480 Pixel)

Standards ISO 2813

GB/T 9754 ASTM D 523 ASTM D 2457

Measuring surface 20 °: 10x10 mm

60 ° : 9x15 mm 85 ° : 5x36 mm

Measuring range 20 °: 0 ... 1000 GU

60°:0 ... 1000 GU 85°:0 ... 160 GU

Readability 0.1 GU

Repeatability Measuring range 0 ... 10 GU: ±0.1 GU

Measuring range 10 ... 100 GU: ±0.2 GU

Measuring range 100 ... 1000 GU: ±0.2 GU (%)

Reproducibility Measuring range 0 ... 10 GU: ±0.2 GU

Measuring range 10 ... 100 GU: ±0.5 GU

Measuring range 100 ... 1000 GU: ±0.5 GU (%)

Chromaticity Meets CIE 1931 (2 °) under a CIE C - light source

Measurement accuracy $\pm 1.2 / \pm 1.2 \%$

Measuring time 1 second

Dimensions 160 x 75 x 90 mm

Weight 350 g

Menu language English, Chinese

Power supply 3200 mAh Li-ion rechargeable battery

Interface USB / RS-232

Measurement memory Based measurement: 1000

Statistical mode: 5000

Continuous measurement: 5000

Software Included in delivery

Ambient temperature $0 \dots +40 \,^{\circ}\text{C}$ Storage temperature $-20 \dots +50 \,^{\circ}\text{C}$

Relative humidity <85 % rel. humidity (not condensing)

Delivery Contents

1 x glossmeter PCE-IGM 100, 1 x evaluation software (auf CD-ROM), 1 x charging adapter, 1 x USB cable, 1 x calibrat x instruction manual