



3M™ Adflo™ Powered & Supplied Air Solutions for Welding & Grinding

3M™ Speedglas™ Welding Helmet 9100 FX-Air – Complete Systems†

†With Grinding Shield underneath

Adflo PAPR

with HE Particle Filter
36-1101-10SW Large
36-1101-20SW X Large
36-1101-30SW 2X Large



With Chemical Cartridge AG/OV and HE Particle Filter
36-3301-10SW Large
36-3301-20SW X Large
36-3301-30SW 2X Large



Fresh Air III Systems

V-100 Cooling Valve
26-5702-00SW V-100*
26-5702-30SWHD 2X Large



*No ADF included.

V-200 Heating Valve
26-5802-00SW V-200*
26-5802-30SW 2X Large



*No ADF included.

3M™ Speedglas™ Welding Helmet 9100-Air – Complete Systems

Adflo PAPR

with HE Particle Filter
35-1101-00SW*
35-1101-10SW Large
35-1101-20SW X Large
35-1101-30SW 2X Large
35-1101-30iSW 2X Large**



*No ADF included.
**New Optics.

With Chemical Cartridge AG/OV and HE Particle Filter
35-3301-00SW*
35-3301-10SW Large
35-3301-20SW X Large
35-3301-30SW 2X Large



*No ADF included.

Fresh Air III Systems

V-100 Cooling Valve
25-5702-10SW Large
25-5702-20SW X Large
25-5702-30SW 2X Large
25-5702-30iSW 2X Large*



*New Optics.

V-200 Heating Valve
25-5802-10SW Large
25-5802-20SW X Large
25-5802-30SW 2X Large



3M™ Speedglas™ Welding Helmet 9100 MP – Complete Systems†

†hard hat rated Type 1

Adflo PAPR



37-1101-00SW*
37-1101-00SWHA**
37-1101-10SW Large
37-1101-20SW X Large
37-1101-30SW 2X Large

*No ADF included.
**High altitude version.

Fresh Air III Systems



V-100 Cooling Valve
27-5702-00SWSR*
27-5702-10SW Large
27-5702-20SW X Large
27-5702-30SW 2X Large

*No ADF included.



V-300 Ambient Air Valve
27-5902-10SW Large
27-5902-20SW X Large
27-5902-30SW 2X Large

3M™ Speedglas™ L-Series Welding Respirators



APF 25
L-705 with Adflo

| Part Number | Description |
|--------------|--|
| 34-0705-SGV | Hard Hat L-705SG wideview faceshield with Speedglas welding filter 9100V and Adflo PAPR with HE filter. |
| 34-0705-SGX | Hard Hat L-705SG wideview faceshield with Speedglas welding filter 9100X and Adflo PAPR with HE filter. |
| 34-0705-SGXX | Hard Hat L-705SG wideview faceshield with Speedglas welding filter 9100XX and Adflo PAPR with HE filter. |



APF 1000
L-905 with Adflo

| Part Number | Description |
|--------------|--|
| 34-0905-SGV | Helmet L-905SG wideview faceshield with Speedglas welding filter 9100V and Adflo PAPR with HE filter. |
| 34-0905-SGX | Helmet L-905SG wideview faceshield with Speedglas welding filter 9100X and Adflo PAPR with HE filter. |
| 34-0905-SGXX | Helmet L-905SG wideview faceshield with Speedglas welding filter 9100XX and Adflo PAPR with HE filter. |

Continued on back



3M™ Adflo™ Powered & Supplied Air Solutions for Welding & Grinding

3M™ M-Series with Adflo



M-207
APF 25



M-307
APF 25



M-407*
APF1000

*M-407 requires SG-50W

35-5401-01 PAPP Assembly with Breathing Tube



Self-Adjusting Breathing Tube SG-30W

Heavy Duty Breathing Tube SG-40W

Sound Dampening Breathing Tube SG-50W



3M™ Fresh Air III Supplied Air Systems

V-100 Vortex Air-Cooling Valve¹



V-200 Vortemp Air-Heating Valve¹



V-300 Air Regulating Valve¹




V-400 Low Pressure²




¹ Use with airline hose W-9435 (25, 50, 100') or W-2929 Series (25, 50, 100')
² Use with airline hose W-3020 (25, 50, 100')

Accessories



Auto-Darkening Filters



Personal Safety Division
3M Center, Building 235-2W-70
St. Paul, MN 55144-1000
USA
Phone 1-800-328-1667
Web www.3M.com/workersafety

3M PSD products are occupational use only.

3M Personal Safety
Service & Technical Support Center
1-800-243-4630 or visit www.3M.com/workersafety
For a complete listing of parts, visit us at:
www.3M.com/weldingsafety

Note: Welding can create a variety of harmful fumes and gases. When engineering controls are impractical, respirators may be required to help reduce exposures to these airborne welding contaminants.

3M, Speedglas and Adflo are trademarks of 3M. Used under license in Canada. Please recycle. Printed in U.S.A. © 3M 2016. All rights reserved. 70-0716-7191-4

⚠ WARNING

These respirators help protect against certain airborne contaminants. Before use, the wearer must read and understand the User Instructions provided as a part of the product packaging. A written respiratory protection program must be implemented meeting all the requirements of OSHA 1910.134 including training, fit testing and medical evaluation. In Canada, CSA standards Z94.4 requirements must be met and/or requirements of the applicable jurisdiction, as appropriate. Misuse may result in sickness or death. For proper use, see packaging instructions, supervisor, or call 3M OH&ESD Technical Service in USA at 1-800-243-4630 and in Canada at 1-800-267-4414.

⚠ WARNING

This product is designed to help protect the wearer's eyes and face from harmful radiation including visible light, ultra-violet radiation (UV), infra-red radiation (IR), sparks and spatter resulting from welding processes. These products must be used only by qualified persons who are properly trained in their use and maintenance. Misuse may result in permanent eye injury and vision loss. Always wear ANSI Z87.1 compliant safety spectacles in addition to any welding helmet. For proper use, see supervisor, or User Instructions or call 3M in U.S.A. 1-800-243-4630. In Canada, call Technical Service at 1-800-267-4414.