



1010a IAQ Meter

APPLICATIONS

- Check ambient CO and CO₂ levels in work and living spaces
- Monitor results of air control systems
- Ambient air temperature and Humidity
- Test dew point and wet bulb humidity



FEATURES & BENEFITS

- Calculate percent outside air to maintain acceptable CO₂ levels in buildings and work spaces
- Measure and display Carbon Dioxide (CO₂) and Carbon Monoxide
- Measure ambient air temperature
- Measure relative humidity, dew point and wet bulb
- Log up to 4,000 readings in 1 second to 23 hour 59 minute intervals
- Download to a computer using the A368 USB cable

MEASUREMENTS

CO ₂	0 to 5000ppm
Temperature	-4 to 140°F (-20 to 60°C)
Relative Humidity	5 to 95%
Dew Point	-47 to 135°F (-44 to 57°C)
Wet Bulb	3 to 135°F (-16 to 57°C)
CO	0 to 500ppm

RANGES