



American Hakko Products, Inc.

# PRODUCT BULLETIN

**Bulletin No:** PB284

**Issue Date:** 11-7-2008

**Description:**

New Factory Burn-in Process for Hakko HJ5000 Heat Gun

**Applies To:**

HJ5000; HJ5000/P; HJ5000-RC-B; HJ5000-RC-G;  
HJ5000-RC-O; HJ5000-RC-R

**Specification:**

Unchanged

**Comments:**

During the manufacturing process, residues are left on the heating element assembly which can cause light smoke and/or odor for the first few minutes of operation of a new heat gun. Due to customer concerns over the visible smoke, all HJ5000 heat guns are now burned in at the factory to burn off the manufacturing residue on the heating element assembly.

**Available:**

From HJ5000 shipments September 22, 2008 forward



From...

For additional information:

- End-User Customers – Call Customer Support at 1-800-88-HAKKO (42556)
- Authorized Distributors – Call Distributor Support at 661-294-0090

American Hakko Products, Inc.  
28920 Avenue Williams.  
Valencia, CA 91355  
Tel: (661) 294-0090  
Fax: (661) 294-0096  
www.HakkoUSA.com  
AHP14 Rev 2007-12