



---

**PCN# : P63BAAB**  
**Issue Date : Mar. 28, 2016**

**Information Only Notification**

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

**Implementation of change:**

Description of Change (From) :

1. Figure 15 (page 13), Figure 25 (page 29): Block diagrams do not have added note on TVS selection
2. Table 29, Note 25 (page 26), Includes "or Test Modes" in first sentence.
3. No detail on TVS selection.

Description of Change (To) :

1. Figure 15 , Figure 25 : Block diagrams updated to add TVS Diode selection reference
2. Table 29, Note 25 (page 26) , removed unnecessary word( "or Test Modes") in first sentence.
3. "Appropriate TVS selection' section with Table 34 is added on page 30.

Reason for Change:

This is a Datasheet change only.

The datasheet is being updated to add more details and guidelines to customers in regards to selecting appropriate TVS Diodes to use with the FSA9682.



---

**Affected Product(s):**

|            |  |  |
|------------|--|--|
| FSA9682UCX |  |  |
|------------|--|--|