

# Contact / Non-Contact **Tachometer with Laser** Model **R7150**



### **Features**

- Dual function unit with both contact and non-contact capabilities
- Provides fast and accurate RPM measurements of rotating objects and surface speed measurements m/min (meter per min) and ft/min (feet per min)
- Laser provides improved accuracy at a greater distance
- Internal memory recalls min/max and last value
- Large LCD Display reverses depending on measurement mode
- Includes reflective tape, large and small cone tip adapters, funnel adapter, wheel adapter, batteries, and hard carrying case.

# **Specifications**

RPM Range (Contact): O.5 to 19.999 RPM Range (Photo): 10 to 99,999

0.05 to 1,999.9 m/min Surface Speed Range:

0.2 to 6,560 ft/min

Resolution: Photo: 0.1 RPM (≤999.9)

1 RPM (>1000)

Contact: 0.1 RPM (≤999.9)

1 RPM (>1000)

Surface: 0.01 m/min (≤99.9)

0.1 m/min (≥100) 0.01 ft/min (≤999.9) 1 ft/min (≥1000)  $\pm(0.05\% + 1 \, dgt.)$ 

Basic Accuracy:

Dimensions:

General Specifications

Visible Indicator: Yes (Laser)

Target Distance: 6.5ft (2000mm) (Photo)

Response Time:

Sampling Time: Photo: 1 sec (over 60 RPM) Contact: 1 sec (over 6 RPM)

5 Digit LCD Display Display Size/Type:

Auto Shut Off: Yes

Internal Memory: Max. Min and Last

Laser Class: Class II Low Battery Indicator: Yes

Power Supply: 4 x AA Batteries

**Product Certifications:** CF

Operating Temperature: 32 to 122°F (O to 50°C) Storage Temperature: -4 to 140°F (-20 to 60°C)

Operating Humidity: 10-90%

> 8.5 x 2.6 x 1.5" (215 x 65 x 38 mm)

Weight: 10.6oz (300g)

## TECHNICAL DATA





Model	Description
R7150	Contact / Non-Contact Tachometer
AS-35C	Replacement Measuring Wheel
CONE	Replacement Cone Tip
RT100	Reflective Tape
CA-05A	Soft Carrying Case
C-820	Soft Carrying Case
R7150-NIST	Contact / Non-Contact Tachometer & NIST