


CT Meter

AC Current Measurement When Using Current Transformers



Easy to Use. Easy to Read.



Featuring an acclaimed easy-to-read display, combined with easy-to-use programming software and a high resolution input, the CT Meter is designed specifically for use with current transformers.

Accurately measuring up to 10,000 amps when used with an external current transformer, the CT Meter's unique display includes three-color dynamic backlighting and programmable scale, now with 10 alarm set-points, linear and non-linear scaling and delayed alarm activation.

The customizable four-character message display and scalability enable users to tailor the meter to display critical parameters to their desired specifications. The set-points, coupled with the backlighting allows operators to be visually alerted when a parameter is out of range. The two outputs can be used to connect the APM to other systems in the process.



Key Features

Unique Display

- · 40 segment bar graph display
- · Large 4-digit display
- Separate Starburst display area for annunciators, custom messages and alarm information
- · Dynamic backlight color


Visibility

- · User-adjustable backlight brightness and colour
- · Large display
- Wide viewing angle (horizontal and vertical)
- · Custom annunciators

Programmable

- · Scale (offset, gain and linear) and Range (min and max)
- · User selectable backlight color and intensity
- *NEW* 20 point non-linearization scaling for non-linear sensors e.g. thermocouples and pressure transducers
- *NEW* Ten independent alarm set-points
- *NEW* Configurable digital output delays (control the time output stays open/closed - .5 seconds - 120 seconds)

Dimensions:



Panel cutout: 68mm x 68mm [2.68" x 2.68"] as per DIN43700/IEC61554

INPUT CURRENT

Range (CT Output Current) 0 - 5A Range (via External CT) Accuracy

ENVIRONMENTAL

Temperature - operating -10 to +60°C Temperature - storage -40 to +70°C IP rating (from the front) IP65 NEMA rating (from the front)

POWER SUPPLY

Nominal Input

DISPLAY

Number of digits Digit height Number of message characters Backlight colours LCD display

OUTPUTS

Max voltage Max current Analogue output CERTIFICATION 0 - 10,000A 0.5%

Type 4 & Type 12 (UL50)

12-24VAC or DC

4

12mm [0.47"]


Red, Green, White Positive or Negative

> 34\/ 500mA

4-20mA UL, cUL, CE, UKCA

Easy To Use Software

Just plug into any USB port on your PC, run the freely available APM Configurator application and you're off. No drivers required.











Part Numbers:

APM-CT-APO APM-CT-ANO 022128-01

APM CT Meter, Positive LCD, With Outputs APM CT Meter, Negative LCD, With Outputs

USB Cable

022150-01 APM Evaluation Kit

BY REQUEST: Modbus Connectivity

APM-CT-APS APM CT Meter, Positive LCD with Modbus APM-CT-ANS APM CT Meter, Negative LCD with Modbus

Full specifications available online www.trumeter.com/apm



6601 Lyons Rd, Suite H-7 Coconut Creek, Florida FL 33073,

Tel: +1 954 725 6699 Email: sales.usa@trumeter.com Trumeter (Europe)

Trumeter Pilot Mill, Alfred Street Bury, Lancashire Tel: +44 161 674 0960 Email: sales.uk@trumeter.com Lot 5881, Lorong Iks Bukit Minyak 1 Taman Perindustrian Iks, 14000 Bukit Tengah

Penang, Malaysia Web: www.idtworld.com Tel: + 604 5015700

Email: sales.my@idtworld.com