


M 2:1

Leiterplattenbohrbild
PCB drillhole pattern



Dieser Bereich muß gleiches Potential auf der LP-Oberfläche haben

This area must have same electrical potential on surface of PCB



alle Löcher/
all holes

214786	M4
214785	M3
214784	6-32UNC
214783	8-32UNC
Id.-Nr.: Part No.	Gewinde Thread

Information:	Tolerances	 All Dimensions in mm	Scale	5:1
	All rights reserved. Only for Information. To ensure that this is the latest version of this drawing, please contact one of the ERNI companies before using.		Designation SVA 10-polig TL Power Bug 10 pin TL	
Subject to modification without prior notice. Drawing will not be updated.		 www.ERNI.com	204819	
d	23.11.2020		Class EPSVA	
Index	Date	I A3		

Copyright by ERNI GmbH
Proprietary notice pursuant to ISO 9006 to be observed.