

an individual temperature series. Easybraid oriers a wide variety of tip geometries from 0.4mm fine point tip to 5m chisel. The length and geometry of a tip will have an influence on the tip idle temperature. To accurately measure idle temperature it will depend greatly on the measurement method, technique and equipment used. Two different methods or the use of alternative equipment will produce different test results.

² Please refer to <u>http://www.rohs.gov.uk</u> for details on RoHS Compliance.

Copyright © 2010 Easybraid Co. All Rights Reserved