

## Test Procedure for the NCP331SNT1GEVB Evaluation Board

- 1. Connect Vin= 3 V between IN and GND
- 2. Check Vout = 0
- 3. Set EN = 2V
- 4. Check Vout = Vin
- 5. Set EN=GND
- 6. Check Vout = 0
- 7. Disconnect Vin