

∧ CAUTION



The Meter produces a visible laser beam which emerges from the front of the Meter.

It is a Class 2 laser product in accordance with: IEC60825-1: 2007 "Radiation safety of laser products"





0.00 ft

0'00" 1/32*

0.000 in

0 in 1/32

* default

())) On/Off

-`On/Off


=

=

Clear

Quick Reference Guide

FLUKE



Buttons

- Measure/Min Max/Power On
- 2. Plus (+)/Scroll Up
- Minus (-)/Scroll Down 3.
- Area/Volume 4
- 5 Memory

1.

- 6. Clear/Off
- 7 Reference/Units
- 8 Timer
- Indirect Measurement 9 (Pythagoras)/Stake Out

PN 4117715 June 2012 © 2012 Fluke Corporation. All rights reserved.

