

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with 19 columns of Dry Bulb Readings (Fahrenheit) and 19 rows of Depression of Wet Bulb (Fahrenheit) from 21 to 32. Includes instructions for use and notes.

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with 19 columns of Dry Bulb Readings (Fahrenheit) and 19 rows of Depression of Wet Bulb (Fahrenheit) from 1 to 20.

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with 21 columns of Dry Bulb Readings (Celsius) and 19 rows of Depression of Wet Bulb (Celsius) from 10.5 to 20.0. Includes instructions for use.

RELATIVE HUMIDITY TABLES FOR WHIRLING PSYCHROMETER

Table with 21 columns of Dry Bulb Readings (Celsius) and 19 rows of Depression of Wet Bulb (Celsius) from 0.5 to 10.0.