


REVISION A

CABLE APPLICATION VIEWS



1A. PRE-TIN CABLE OUTER JACKET OVER APPROX. LENGTH SHOWN.

1B. TRIM CABLE TO EXPOSE CENTER CONDUCTOR AS SHOWN.

1C. POINT CENTER CONDUCTOR AS INDICATED.

1D. SLIDE DIELECTRIC STOP ONTO CENTER CONDUCTOR AGAINST CABLE FACE.



2B. SOLDER CABLE JACKET TO BODY WHERE SHOWN APPLYING HEAT TO EXTENDED BODY TAIL.

