


# Accessories

## Auxiliary contact


### Front mount blocks

### Side mount blocks


#### Screw clamp connection




#### Fast-on connection



#### Cage clamp connection





#### Solder pin connection



## Catalog No.



Connection type	Applying contactors	Mounting type	Composition	Catalog no.
<b>Screw clamp</b>	CGMS-, CGMSS-, CGMUS- 6A(D) 9A(D) 12A(D) 16A(D)	Front mount	2NO	AX-2MS20
			2NC	AX-2MS02
			1NO+1NC	AX-2MS11
			4NO	AX-4MS40
			3NO+1NC	AX-4MS31
			2NO+2NC	AX-4MS22
			1NO+3NC	AX-4MS13
			4NC	AX-4MS04
			Side mount	1NO
		1NC	AX-1MS01	
<b>Fast-on</b>	CGMF-, CGMSF-, CGMUF- 6A(D) 9A(D) 12A(D) 16A(D)	Front mount	2NO	AX-2MF20
			2NC	AX-2MF02
			1NO+1NC	AX-2MF11
			4NO	AX-4MF40
			3NO+1NC	AX-4MF31
			2NO+2NC	AX-4MF22
			1NO+3NC	AX-4MF13
			4NC	AX-4MF04
			Side mount	1NO
		1NC	AX-1MF01	
<b>Cage clamp</b>	CGMC-, CGMSC-, CGMUC- 6A(D) 9A(D) 12A(D) 16A(D)	Front mount	2NO	AX-2MC20
			2NC	AX-2MC02
			1NO+1NC	AX-2MC11
			4NO	AX-4MC40
			3NO+1NC	AX-4MC31
			2NO+2NC	AX-4MC22
			1NO+3NC	AX-4MC13
			4NC	AX-4MC04
			Side mount	1NO
		1NC	AX-1MC01	
<b>Solder pin</b>	CGMP-, CGMSP-, CGMUP- 6A(D) 9A(D) 12A(D) 16A(D)	Side mount	1NO	AX-1MP10
			1NC	AX-1MP01

**CGMS-12A**  
+  
**AX-4MS**




0.21kg

**CGMS-12D**  
+  
2 × **AX-1MS**




0.21kg

**AX-4MS**




0.04kg

**AX-2MS**



0.03kg

**AX-1MS**



0.02kg