

## Laboratory Balance PCE-BSH 10000




PCE-BSH 10000 is a an accurate compact digital scale or balance with piece or part counting functionality. Ideal for use in kitchens, laboratories and offices, this precision scale has a USB port for data transfer and printing.

Functionality: TARE (mid range), ZERO, auto calibration (CAL - requires external weight, not included), piece counting (PCS), auto power on / off, backlight on / off

Low battery, negative value, stability and overload indication

By pressing the PRINT key, the current reading is sent out via the USB port (Depending on the setting, the scale either sends out the reading when the PRINT key is pressed, continuously or once the reading is stable)





www.pce-instruments.com


## **Specifications**

- Weighing range: 0.6 ... 10000 g / 0.0014 ... 22 lbs
- Readability or resolution: 0.2 g
- Accuracy: ± 0.6 g
- Weighing unit selections: g, oz, lb, dwt, ozt, ct, tl.T, tl.H, tl.J, GN, dr, MM, ToLA, GSM, TAR, TMR
- Display: LCD with backlight, 20 mm / 0.79" character height
- TARE: Multiple taring over full range
- Data interface: USB port
- Power supply: 12 V / 500 mA electric power adapter (included) or six 1.5 V AA batteries
- Operating temperature: 0 ... +40 °C / +32 ... +104 °F
- Weighing platform dimensions: 160 x 180 mm / 6.3 x 7.08"
- Overall dimensions: 200 x 265 x 100 mm / 7.87 x 10.43 x 3.94"
- Overall weight: Approx. 1800 g / 3.94 lbs (without batteries)

See user manual for complete technical specifications.

## More information







www.pce-instruments.com