



Test Procedure for the NCP459FCT2GEVB Evaluation Board

1. Connect strap between IN and Vbias
2. Connect 3.2 V between IN and GND
3. Check $V_{out} = 0$
4. Set EN = 2V
5. Check $V_{out} = V_{in}$
6. Set EN = 0V
7. Check V_{out} decreases down to GND
8. Disconnect V_{in}