


F:\DWG\MISC\MKTG\SFM-1XX-XX-XXX-D-XXX-X-XX-MKT.SLDDRW



*FOR MACHINE LOADING OF TUBES FOR PARTS W/O PADS USE PT-1-24-14-09, TP-24-02

5 POS -01 AND -03 LEAD STYLES MAY BE TUBED USING PT-1-24-15-09, TP-24-02 2 POS -X1 STYLE TO BE TUBED IN PT-1-24-15-09

-X1-D-P, -X1-D-LC-P (WITH P&P PAD), X1-D-A-P -X2-D, -X2-D-K, -X2-D-LC (NO P&P PAD),

-X2-D-P, -X3-D-P, -X2-D-LC-P (WITH P&P PAD), -X2-D-A-P,

-X2-D-A, -X2-D-K-A, -X2-D-LC-K, -X2-D-SNX

-X3-D-A-P, -X2-D-P-SNX

-01-DS, -02-DS, -03-DS

PACKAGE PARTS IN TUBES AS SHOWN (SEE NOTE 4)



PT-1-24-02-17

PT-1-24-13-09

PT-1-24-01-60


PT-SFM004-X1-X3-D


TP-09


TP-24

TP-03

TP-24-02








REVISION DX







PACKAGING VIEW -TR: TAPE AND REEL