
MITSUMI

Temperature and Humidity sensor MW3827ARRE Data Sheet

Description



The MW3827 is a combined relative humidity and temperature sensor module. The dual sensor is also combined with our custom analog front end to provide a fully calibrated and temperature compensated digitized I²C output. The MW3827 proprietary polymer and parallel plate capacitive structure provides excellent robustness and reliability. No complicated sensor drive or control circuit is required, and high performance sensing is achievable only with the MW3827 and an external microcontroller which works as a host.

Features

- Small package: $2.0(W) \times 2.0(D) \times 0.8(H)$ mm
- Operating temperature ranges -40~+105°C
- Operating Humidity ranges 0~100%RH
- Supply voltage 2.2~5.5V
- Current consumption 8.97µA Typ. (@1sample/sec.)
- Current consumption at sleep 0.85µA Typ.
- Output corrected humidity value with repeatability of 0.015%RH (I²C)
- Equipped with a heater for checking operation
- 8-bit I²C address 50h(Write), 51h(Read)
- RoHS compliant
- Halogen-free

Contents

Description	
Features	
BLOCK DIAGRAM	
PIN CONFIGURATION	
TERMINAL EXPLANATIONS	
EQUIVALENT CIRCUIT OF THE PINS	
ABSOLUTE MAXIMUM RATINGS	7
RECOMMENDED OPERATING CONDITIONS	
Power-on sequence	
Reapply voltage sequence	
ELECTRICAL CHARACTERISTICS	
Analog characteristics	
Humidity sensor characteristics	
Temperature sensor characteristics	10
Digital I/O DEFINITION OF CHARACTERISTICS	11
FUNCTION	
Description of operation method	13
Description of state (Sleep State / Measurement State)	13
About system design	13
Detailed description of Measurement state	
Heater function	
State transition table	
State transition diagram	
Control register	
Status register	20
Method of calculation to temperature and humidity values	
SERIAL INTERFACE	
I ² C format	
Write format	
Read format	
Combined format	
I ² C AC characteristics	
TYPICAL APPLICATION CIRCUIT	
TYPICAL PERFORMANCE CHARACTERISTICS	
DIMENSIONS	
MARKING CONTENTS	
CONDITION FOR PACKAGE MOUNTING	
Design example of mount pad	
Pb-Free recommended profile condition	
Rehydration treatment	
Storage method	
PACKAGING SPECIFICATION	

BLOCK DIAGRAM




Fig.1 Block diagram

PIN CONFIGURATION




Fig.3 Pin configuration (Bottom view)

TERMINAL EXPLANATIONS

Table.1 Pin table

No.	Pin Name	Туре	Function
1	SDA	I/O	Serial Data (Input and output) for I ² C communication(SDA)
2	DRDY	0	Output terminal which notifies the completion of temperature and humidity measurement and calculation correction (positive logic)
3	GND	-	GND
4	VREG	0	VREG Connect to a 0.1μ F capacitor to GND. (Note ¹) Do not connect anything to it other than. If it is not connected, the sensor may be destroyed.
5	VDD	Ι	Power supply (Connect to bypass capacitor;1µF)
6	SCL	I/O	Serial clock for I ² C communication(SCL)

note¹: It is recommended to use a capacitor with a nominal value of 0.1μ F, an allowable capacitance value of $\pm 10\%$ or less, and thermal characteristics of $\pm 15\%$ or less.

EQUIVALENT CIRCUIT OF THE PINS

Table.2 Pin table						
Pin Name	Туре	Equivalent Circuit of the pins				
SCL SDA	I/O	SCL SDA GND W-D-D				
DRDY	Ο					
VREG	0					
VDD	Ι	VDD GND 777				

ABSOLUTE MAXIMUM RATINGS

(Unless	otherwise	specified.	Ta=25°C.	VDD=3.3V)	
	0111033	OUTCI WISC	specificu,	1u-25 C,	vDD-5.5v)	

Item	Symbol	Min.	Max.	Unit
Storage temperature range	T _{STG}	-40	+125	°C
Analog supply voltage	VDD _{MAX}	-0.3	+6.0	V
Digital input voltage	VDIN _{MAX}	-0.3	VDD+0.3	V


RECOMMENDED OPERATING CONDITIONS

(Unless otherwise specified, Ta=25°C, VI

Item	Symbol	Min.	Max.	Unit
Operating temperature range	T _{OPR}	-40	+105	°C
Operating humidity range	H _{OPR}	0	100	%RH
Analog supply voltage	VDD _{OPR}	+2.2	+5.5	V
Digital input voltage	VDINOPR	0	VDD	V

Power-on sequence

When the power is turned on, access the device at least 15msec. after reaching 90% of the applied voltage. (note²)





Reapply voltage sequence

When turning on the power again, wait until VDD drops below 0.1V, and then turn on the power again after at least 6msec has elapsed.




Fig.5 Reapply voltage Sequence

note²: The above power-on sequence operation may fail when the power is turned on, for example, if the power waveform is not appropriate. If the power-on sequence fails, MW3827 transitions to a setting that rejects I²C communication, reflecting the error state in the ERR_BL bit of the status register, in order to prevent the error from continuing to operate in the abnormal state. Refer to the <u>Status register</u> for details on how to check and return.

ELECTRICAL CHARACTERISTICS

Analog characteristics

(Unless otherwise specified, Ta=25°C, VDD=3.3V)

Item	Symbol	Condition	Min.	Тур.	Max.	Unit.
Current consumption	I_{DD}	One Shot Operation 1sample/sec. (note ³)	-	8.97	14.2	μA
Current consumption at Sleep	I_{DDSL}	At Sleep state (note ⁴)	-	0.85	1.6	μA
Current consumption at Standby	I_{DDSB}	At Standby state (note ⁴)	-	0.95	1.8	μA
Current consumption at Measurement	I_{DDM}	At Measurement state (note ⁴)	-	1120	1420	μA
Current at Heater-ON (note ⁵)	I _{HEAT}		-	10	(TBD)	mA
VPEC voltage	V_{RGSL}	At Sleep state (note ⁴)	1.71	1.8	1.89	V
VREG voltage	V _{RGACT}	At Active	1.71	1.8	1.89	V

note³: The average of one sample per second by One Shot Operation.

note⁴: For details of each state, refer to <u>Description of the state</u> or <u>State transition diagram</u>. note⁵: About setting heater, please see <u>Heater function</u>.

Humidity sensor characteristics


(Unless otherwise specified, Ta=25°C, VDD=3.3V)

Item	Symbol	Condition	Min.	Тур.	Max.	Unit
Humidity accuracy	H_{acc}	25°C, 50%RH	-	±2	-	%RH
Humidity repeatability	H _{rep}		-	0.015	-	%RH RMS
Humidity hysteresis	H_{hys}	Ta=25°C	-1	-	+1	%RH
Humidity response time	t _{HRESP}	10⇔90%RH @Ta=25°C, τ=63% Air flow 1m/s	-	6	-	sec.

Temperature sensor characteristics

(Unless otherwise specified, Ta=25°C, VDD=3.3V)

Item	Symbol	Conditions	Min.	Тур.	Max.	Unit
Temperature accuracy	T_{acc}	Ta = 25°C	-0.5	-	+0.5	°C



Digital I/O

(Unless otherwise specified, Ta=25°C, VDD=3.3V)

Item	Symbol	Conditions	Min.	Тур.	Max.	Unit
High level input voltage	V_{IH}	SCL, SDA	0.7 × VDD	-	VDD +0.3	V
Low level input voltage	V _{IL}	SCL, SDA	-0.3	-	0.3 × VDD	V
Output voltage High level	V _{OH}	DRDY I _{OH} =-3mA	0.8 × VDD	-	-	V
Output voltage Low level	V _{OL}	SCL、SDA、DRDY I _{OL} =3mA	-	-	0.4	V

DEFINITION OF CHARACTERISTICS

To be released

FUNCTION

Description of operation method

MW3827 operates on the I²C interface and the slave address (7-bit) is 28h. The operation is controlled by specifying the control register in the write format. When accessed in the read format, the measurement result can be read as a digital value. For the method of calculating the digital value to temperature and humidity, refer to <u>Method of calculation to temperature and humidity values</u>. The status register reflects the operating state and reads the register value by specifying the register address in the combination format

Description of state (Sleep State / Measurement State)

MW3827 transitions to the state according to the control register settings. There are two types of state: Sleep state and Measurement state. Additionally, there are two types of Measurement state: One Shot Operation and Repeat Operation. The outline is shown below

Sleep state ··· Waiting state.

Measurement state

- 1) Repeat Operation ··· Repeat measurement for each set T_{Standby}.
- 2) One Shot Operation ··· Only one time measurement.

For details of each state, refer to State transition table and State transition diagram.

About system design

1) Repeat Operation

This is a MW3827 initiative and is intended to be timing-controlled. MCU is used in the basic Sleep. DRDY of MW3827 is used to release Sleep of the MCUs at regular intervals to reduce the current of the entire system.

2) One Shot Operation

This operation is based on the assumption that the timing should be controlled under the initiative of the MCU. Measurement is instructed by the MCU each time. After measuring is complete, MW3827 transitions to Sleep and waits with minimal current savings.

Detailed description of Measurement state

Repeat Operation

Repeat Operation is measured continuously according to $T_{Standby}$ setting. Set the operation state setting bit SET_STATE [2:0] of the control register to 001b. Set the standby time $T_{Standby}$ for repeat measurements with the Standby time setting bit TSTBY[2:0]. After the measurement is completed, the previous measurement results are discarded and the new measurement results are retained.




Fig.8 Timing chart for Repeat Operation

One Shot Operation

One Shot Operation is a single measure that automatically returns to sleep without transitioning to Standby state. Set the operation state setting bit SET_STATE [2:0] of the control register to 001b and Standby time setting bit TSTBY [2:0] to 111b. After the measurement is completed, the previous measurement results are discarded and the new measurement results are retained.




Fig.9 Timing chart for One Shot Operation

Heater function

MW3827 is equipped with a heater for functional verification. When the heater is enabled (EN_HEATER bit in the control register is 1b), it can be checked to see if it is functioning as a sensor by checking that the temperature is rising and the humidity is falling. Please wait about 20 seconds after activating the heater. Be careful not to forget to return the heater to OFF (EN_HEATER bit in the control register to 0b) after the operation check is finished. The initial value of EN_HEATER bit in the control register is 0b (Heater Off).

MW3827 is equipped with a function to detect abnormal heater current to prevent excessive heat generation. The ERR_HEAT bit in the status register indicates the monitoring result of the abnormal current of the heater.

State transition table

Table.3 State transition table

	State						
SET_STATE [2:0]	Sleep	Standby	Measurement				
Sleep (000b)	Keep state	Transit to Sleep	After AD conversion, transit to Sleep				
Measurement (001b) Repeat Operation	Transit to Measurement	Transit to Measurement	Keep state				
Measurement (001b) One Shot Operation	Transits to Measurement, transits to Sleep after AD conversion	Transits to Measurement, transits to Sleep after AD conversion	Transits to Sleep after AD conversion				
Reset & Sleep (100b)	After all register reset and Boot Load, transit to Sleep	After all register reset and Boot Load, transit to Sleep	After all register reset and Boot Load, transit to Sleep				

When there is error in Boot Load, the MW3827 will be waiting in the sleep state, set ERR_BL "1". Please see <u>Status register</u> for details

State transition diagram




Fig.10 State transition diagram

Notes on transitioning from a Repeat Operation to another

When MW3827 is in Repeat operation and the device is accessed during the transition from Standby to Measurement, it returns an NACK as a communication error. If this happens, wait at least 3msec after a communication error occurs before accessing the device again.

Control register

			Tub	IC. I DCtuli		Table.4 Detail of control register						
Addr	Initial	Bit7	Bit6	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	R/W		
0Ch	00h	Reserved		TSTBY[2:0]		EN_ HEATER	SET_STATE[2:0]			R/W		
001b : Fo 010b : Tst 011b : Tst 100b : Tst 100b : Tst 101b : For 110b : For 111b : On •EN_HEATER Set Heater O •SET_STATE Set operation 000b : Tra 001b : Tra 010b : Pro 011b : For 100b : Res 101b : For 100b : For 100b : For 100b : For	110b is set T or manufactur andby 100ms andby 400ms andby 1000ms r manufacture r manufacture e Shot (Reture R : n or Off. "0" [2:0] :	rer (note ⁶) rer (note ⁶) er (note ⁶) er (note ⁶) rns to Sleep is Heater-Ol p". surement". ngs er (Test stat eset to initia er (Test stat er (Test stat	without tr F. ``1″ is H e) (note ⁶) lize all reg e) (note ⁶)	ansit to Sta eater-ON.	ndby)			o, this settir	ng is ignore	d.		

Table.4 Detail of control register

Important : Don't send data the other register in this specification sheet. It could lead to operate out of specification

note⁶: Setting for inspection. Be care not to set it. If it is set incorrectly, perform Reset & Sleep. note⁷: After Reset & Sleep, wait for at least 3msec before accessing the device.

Table.5 Detail of status register										
Addr	Initial	Bit7	Bit6	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	R/W
09h	00h	Reserved	ERR HEAT	ERR_ BL	ERR INFO	RDY DATA		STATE[2:0]		R/-
•ERR_HEAT : Overcurrent detection signal for heater current. 0: Normal, 1: Abnormal If an overcurrent flows when the heater is used (EN_HEATER=1), the heater operation is stopped and this bit is set to "1". (Overcurrent threshold is 140mA; design value.) Clear condition: Reset & Sleep (SET_STATE[2:0]を 001b) or EN_HEATER=0										
•ERR_BL : NVM BootLoad error detection signal. 0: Normal, 1: Abnormal When this signal becomes "1" (Abnormal), slave address (7-bit) is changed to "4Ch" and transit to error state. Clear condition: Reset & Sleep (SET_STATE[2:0]001b) or being turned on again after power supply is cut off.										
•ERR_INFO : Signal informing prohibition setting of control register. 0: Normal, 1: Abnormal If it is set to prohibit, it transits to sleep state without starting operation. At this time, the ERR_INFO bit of the status register becomes "1". Clear condition: Writing the correct settings starts normal operation. At that time, ERR_INFO is set to "0".										
•RDY_DATA : Signal determining acquisition of conversion result. This bit becomes "0" at the time of conversion setting and "1" after conversion completion. This bit is cleared to "0" by reading the result or Reset & Sleep when this bit is "1".										
 STATE[2:0] : Represents MW3827 state. 000b : Sleep 001b : Measurement (Repeat Operation or One Shot Operation) 010b, 011b : For manufacturer In normal operation, this state is not entered. If this condition stops, Reset & Sleep MW3827 or being turned on again after power supply is cut off. 100b : None 100b : None 										
	100b : None 101b : Standby(Temporary state)									

110b : For manufacturer

111b : None

Method of calculation to temperature and humidity values

The read digital value is the corrected value that is automatically performed for each AD conversion. Therefore, the user can obtain the temperature and humidity using the formula shown below.

Temperature = $(16\text{-bit digital value} - 2^{15}) / 50 + 25$ [°C] Humidity = $1000 * (16\text{-bit digital value} - 2^{15}) / 2^{18} - 20$ [%RH] Example for temperature calculation Temperature = $(34003 - 2^{15}) / 50 + 25$ = (+1235) / 50 + 25= (24.7) + 25= 49.70 [°C]

Example for humidity calculation Humidity

 $= 1000 * (51118 - 2^{15}) / 2^{18} - 20$ = 1000 * (+18350) / 2¹⁸ - 20 = (69.9997) - 20 = 49.9997 [%RH]

Table.6 Correspondence table between 16-bit digital value and temperature

16-bit digital value	16-bit digital value – 2 ¹⁵	Temperature [°C]
65535 (FFFFh)	32767 (7FFFh)	680.34
32769 (8001h)	1 (0001h)	25.02
32768 (8000h)	0 (0000h)	25.00
32767 (7FFFh)	-1 (FFFFh)	24.98
0 (0000h)	-32768 (8000h)	-630.36

Table.7	Correspondence	table between	16-bit digital	value and humidit	.V

16-bit digital value	16-bit digital value – 2 ¹⁵	Humidity [%RH]
65535 (FFFFh)	32767 (7FFFh)	104.9962
64225 (FAE1h)	31452 (7AE1h)	99.9989
51118 (C7AEh)	18350 (47AEh)	49.9997
38011 (947Bh)	5243 (147Bh)	0.0005
32769 (8001h)	1 (0001h)	-19.9962
32768 (8000h)	0 (0000h)	-20.0000
32767 (7FFFh)	-1 (FFFFh)	-20.0038
0 (0000h)	-32768 (8000h)	-145.0000

SERIAL INTERFACE

The MW3827 supports I^2C of Fast mode (fmax = 400kHz) as an interface for serial communication.


I²C format

The I²C address is 8-bit, including the slave address of the first 7-bits and R/W bit of the remaining 1-bit. Slave address for the MW3827 (7-bit) is 28h. I²C address (8-bit) will be 50h (Write) and 51h (Read) by combining with R/W bit.

Table.8 I ² C address								
		I ² C Address (8-bit)						
	Slave address (7-bit)				R/W bit			
HEX.	A6	A5	A4	A3	A2	A1	A0	K/ VV DIL
50h	0	1	0	1	0	0	0	0
51h	0	1	0	1	0	0	0	1

Write format


This format is used to set the control register (0Ch). Start by sending 8-bit I²C address 50h (Write). After the address is received, ACK is returned to the 9th bit. After that, send 8-bit control register address (0Ch). After the register address is received, ACK is returned to the 9th bit. Then, send 8-bit data according to the control register details.



Important : Don't send data the other register in this specification sheet. It could lead to operate out of specification


Read format

This format is used to read measurement results of temperature and humidity. Start by sending 8-bit I²C address 51h (Read). After the address is received, ACK is returned to the 9th bit. After that, 32-bit data is output in 8-bit units in MSB first. Then, send ACK every 8-bit. As shown, Humi.Data is 16-bit of [15:0] and Temp.Data is 16-bit of [15:0]. It is unnecessary to send register address.



Combined format

This format is used to read register value. Start by sending 8-bit I²C address 50h (Write). After the address is received, ACK is returned to the 9th bit. After that, send an 8-bit control register address (0Ch) or status resister address (09h). The MW3827 will respond with ACK with 9th bit. Then, send 8-bit I²C address 51h (Read). After the address is received, ACK is returned to the 9th bit and 8-bit data is output. For details of register, refer to <u>Control register</u> or <u>Status register</u>.



note⁸: It also supports Repeat start condition.

I²C AC characteristics

* Design assurance items




Fig 14	T ² C	AC	timing	chart
119.11	тC	ЛC	unning	chart

Table.9 I²C AC Characteristics (note⁹) (Unless otherwise specified, Ta=25°C, VDD=3.3V, $C_{OL} \leq 400 pF$)

Items		Fa	ast mo	Unit	
100115	Symbol	min	Тур	max	Unit
SCL clock frequency	f_{SCL}	0	-	400	kHz
Start condition setup time relative to SCL edge	tsusta	600	-	-	ns
Start condition hold time relative to SCL edge	thdsta	600	I	-	ns
Stop condition setup time on SCL	tsusto	600	-	-	ns
Data setup time on SDA relative to SCL edge	tsudat	100	I	-	ns
Data hold time on SDA relative to SCL edge	thddat	20	-	-	ns
SCL rise time	t _{rCL}	-	-	300	ns
SCL fall time	t _{fCL}	10	-	300	ns
SDA rise time	t rDA	-	-	300	ns
SDA fall time	t _{fDA}	10	-	300	ns

note⁹: This product does not have the function to retain data in SDA. Please ensure the hold of SDA with 20nsec for the area where SCL falling edge is not defined.

TYPICAL APPLICATION CIRCUIT





Fig.15 Typical electrical connection

TYPICAL PERFORMANCE CHARACTERISTICS

(Unless otherwise specified, Ta=25°C, VDD=3.3V)



Supply voltage characteristics




Fig.17 Current consumption I_{DD} Temperature characteristics




Fig.19 Current consumption at Sleep I_{DDSL} Temperature characteristics





Fig.21 Current consumption at Standby I_{DDSB} Temperature characteristics








Fig.23 Current at Heater-ON I_{HEAT} Supply voltage characteristics




Fig.25 VREG voltage at Sleep V_{RGSL} Supply voltage characteristics




Fig.22 Current consumption at Measurement I_{DDM} Temperature characteristics




Fig.24 Current at Heater-ON I_{HEAT} Temperature characteristics





Fig.26 VREG voltage V_{RGSL} Temperature characteristics




Supply voltage characteristics


Temperature characteristics

DIMENSIONS


PACKAGE: PLP-6L



MARKING CONTENTS



How to identify 2 characteristics lot numbers.



(1) The 1st digit (①) shows the first half of the year or the latter half.

(2) The 2nd digit (2) shows a production week of mass production.

[How to indicate a production year] First half of the year

The 1st digit (①)					
The last digit of a production year	Mark				
xxx1	1				
xxx2	2				
xxx3	3				
xxx4	4				
xxx5	5				
хххб	6				
xxx7	7				
xxx8	8				
Xxx9	9				
Xxx0	0				

The 2nd digit (②)						
Production week	Mark	Production week	Mark			
1	1	14	E			
2	2	15	F			
3	3	16	G			
4	4	17	Н			
5	5	18	J			
6	6	19	К			
7	7	20	L			
8	8	21	Μ			
9	9	22	Ν			
10	А	23	Р			
11	В	24	Q			
12	С	25	R			
13	D	26	S			

Last half of the year


The 1st digit (①)					
The last digit of a production year	Mark				
xxx1	А				
xxx2	В				
xxx3	С				
xxx4	D				
xxx5	Е				
хххб	F				
xxx7	G				
xxx8	Н				
Xxx9	J				
Xxx0	K				

The 2nd digit (②)					
Production week	Mark	Production week	Mark		
27	1	40	Е		
28	2	41	F		
29	3	42	G		
30	4	43	Н		
31	5	44	J		
32	6	45	К		
33	7	46	L		
34	8	47	М		
35	9	48	Ν		
36	Α	49	Р		
37	В	50	Q		
38	С	51	R		
39	39 D		S		
		53	Т		

CONDITION FOR PACKAGE MOUNTING

Design example of mount pad


UNIT mm



The dimension is for reference only and not guaranteed by design.

To design practically, correction should be made for optimized dimensions considering the effects of the board type to be mounted, mount (soldering) method, type and coating thickness of cream solder.

Pb-Free recommended profile condition



This profile gives recommended values, which are not guaranteed. For mounting the package, evaluate the profile with the equipment, conditions, and materials to be used.

This IC does not support cleaning because the temperature & humidity sensor is exposed on the surface of the package. Therefore, please use a non-cleaning type solder paste for mounting.

- Mounting by wave soldering Wave soldering cannot be used for mounting of this package.
- Mounting by manual soldering

Manual soldering cannot be used for mounting of this package.

Rehydration treatment

It is recommended to perform rehydration treatment after reflow mounting.

Rehydration conditions: 85°C85%RH6hrs

Storage method

[Storage condition]

Store the device under the following conditions.

Temperature	: 5~30°C
Humidity	: 40~70%RH
Storage life	: 1year

If stored in an environment that exceeds the storage conditions, the characteristics may change. Store the product in the original packing bag. For storage after mounting the product, use an ESD bag with a metal layer. Do not use polyethylene ESD bags as they may change characteristics. Do not store this device where a large amount of dust or harmful volatile gas exists, electrostatic is easily charged, condensation is generated, or changes in temperature and humidity are wide, or under the direct sunlight.

[Baking]

If the storage time specified above has passed, mounting by soldering may cause cracks on the moisture absorbed package. Before mounting, the package should be baked under the following conditions. Because the moisture content of the product changes due to heat during baking and reflow, be sure to perform the rehydration treatment after mounting.

Temperature	:125°C
Treating time	:16~24hours

Embossing tapes and reels are not heat-resistant type.

Before baking, the device should be placed in a heat-resistant container.

In consideration of the time-consuming baking process and the possibility of deformed terminal, the device should be mounted promptly within the time observing the storage conditions.

[Handling instructions]

Shipping boxes must be handled with care because any drop or shock may damage the device.

Additionally, the device must be handled in the place with the protection against electrostatic charge and without extreme changes of temperature/humidity.

Be careful not to touch the package opening with fingers. The characteristics may fluctuate due to oils in skin. Note that the characteristics may fluctuate if salt adheres to the package opening.

[Instructions for mounting]

When this product is mounted on the board, the effect from the board may depend on the product mounting direction and position. Board stress (warping, bending, etc.) and mechanical stress (vibration, impact, etc.) may cause fluctuation of electrical characteristics, package crack, chip crack, loss of lead, and others. Therefore, if the effect of the stress is a concern as shown in Figure A, it is recommended to mount this product on the board as shown in Figure B or C.





Figure A Mounting susceptible to the effect of the stress

When this product (lead direction) is mounted in a horizontal direction to a long side of the board, the stress from the board significantly affects leads.



(Mounting direction)

Mounting the product (lead direction) perpendicular to a long side of the board reduces the effect of the stress from the board on the leads.




Figure C Mounting condition with less stress (Mounting position)

Mounting the product in a position away from the board center reduces the effect of the stress from the board on the leads.

Before mounting this product on the board, fully examine other conditions including the radiation performance and mechanical strength of the board as well.

PACKAGING SPECIFICATION

1. APPLICATION LIMIT

IT APPLIES TO THE PACKING SPECIFICATION OF PLP-6L.

2. QUANTITY

- (1) REEL PACKING 4000pcs / REEL
- (2) BOX PACKING MAX 20,000 pcs / BOX (5 REEL)


THE QUANTITY IS FILLED IN THE PACKING SLIP.

3. PACKING SPECIFICATION

(1) HOUSING SPECIFICATION	REFER TO DRAWING
(2) REEL DIMENSIONS	REFER TO DRAWING

(3) BOX DIMENSIONS REFER TO DRAWING

エンボステープ収納仕様 EMBOSS TAPE HOUSING SPECIFICATION



	記号 SYS	AO	BO	W	F	Ε	P1	P2	PO	φ]]O	T	Τ1	¢]1
U	NIT	2.3	2.3	8.0	3.5	1.75	4.0	2.0	4.0	1.5	0.2	1.0	1.05
'	mm	±0,05	±0,05	±0,1	±0,05	±0,1	±0,1	±0,05	±0,1	+0,1 -0	±0,05	±0,05	±0,05

NDTE


1,部品の引き出し方向 IC PULL DUT DIRECTION



- キャリアテープの材質は、帯電防止処理済みとする。
 CARRIER TAPE MATERIAL + DISPOSED ELECTRICATION PREVENTION.
- 3, リーダー部のテープの長さは、部品の入っていないエンボスを40以上 含み、200mm以上とする。 LENGTH OF LEADER TAPE - MORE THAN 200mm INCLUDING 40 OR MORE ENBOSSES IN WHICH NO COMPONENT IS PLACED.
- 4,終端部のテープの長さは、部品の入っていないエンボスを4日以上 含み、160mm以上とする。 LENGTH DF TRAILER TAPE I MORE THAN 160mm INCLUDING 40 DR MORE EMBOSSES IN WHICH NO COMPONENT IS PLACED,

リール寸法 REEL DIMENSIONS


UNITmm



記号 SYM,	φA	φC	ϕN	E	W1	М5
IINTT	180	13	60	2	9.0	11,4
mm	+ 3	±0'5	± 1	±0,5	± 1	±1.0



UNIT mm





MAR NESSRS		
E B PART NO.		
🗿 🧌 DESCRIPTION		
£ € 7/0 MQ.	-	-
백 II NOTE		
TOTALE TY/BOURS	0.11	NOX ERA
	00/	
DATE		
LOT NO.		
R & SPEC. L	1	-

MITSUMI ELECTRIC CO., LTD.

Strategy Engineering Department Semiconductor Business Division

Tel: +81-46-230-3470 / http://www.mitsumi.co.jp

Notes:

Any products mentioned this datasheet are subject to any modification in their appearance and others for improvements without prior notification. The details listed here are not a guarantee of the individual products at the time of ordering. When using the products, you will be asked to check their specifications.