

Accelerometer PCE-VT 3700





Handy entry-level device for vibration monitoring of machines and systems / HOLD function / Peak value measurement / Handheld device for mobile vibration measurement / Automatic ISO 10816-3 evaluation

The accelerometer is ideal for maintenance workers to quickly check vibrating parts, machines and systems. This vibration meter shows the vibration acceleration, vibration velocity and vibration displacement directly on the display. You can use the device to quickly and reliably detect machine imbalances which can lead to, for example, bearing damage. The vibration meter is equipped with a mode that allows a measurement according to ISO 10816-3 to be carried out. The vibration meter analyzes the measured values and automatically shows a good / bad evaluation on the display.

The vibration meter is supplied with a sensor on the spiral cable, magnet adapter, service bag and batteries. The display of the vibration meter is a colored graphic display, which makes operation easier, since all instructions and menu items are shown in plain text. The 12 languages in the menu of the vibration meter are easily switchable.

- ▶ Automatic ISO 10816-3 evaluation
- ► Easy to handle
- ► For mobile vibration measurement
- -The measurement unit can be switched between the metric system and imperial units.
- ► Colored graphic display
- ▶ Peak-hold function

Specifications

Measuring range Acceleration

0.0 - 399.9 m/s² / 0.0 - 15744 in/s²

Resolution $0.1 \text{ m/s}^2 / 3.94 \text{ in/s}^2$

Accuracy @ 160 Hz ±2 %

Frequency range 1 kHz - 10 kHz

10 Hz - 10 kHz

Measuring range Velocity

0.00 - 399.99 mm/s / 0.00 - 15.74 in/s

Resolution 0.01 mm/s / 0.0039 in/s

Frequency range 10 Hz - 1 kHz

Measuring range **Displacement**

0.000 - 3.999 mm / 0.000 - 0.154 in

Resolution $1 \mu m / 39.4 \mu in$

Accuracy @ 160 Hz ±2 %

Frequency range 10 Hz - 200 Hz

Measurement parameters RMS, Peak, Peak-Peak

Crest factor

Units switchable metric / imperial

Display 2.4" LC display

Menu languages English, German, French

Spanish, Italian, Dutch
Portuguese, Turkish, Polish
Russian, Chinese, Japanese

Power supply 3 x 1.5 V AA batteries

Operating and storage conditions $-20 \dots +65 \,^{\circ}\text{C} / -4 \dots 149 \,^{\circ}\text{F}$; $10 \dots 95 \,^{\circ}\text{M} \cdot \text{H}$.

Dimensions 150 x 80 x 38 mm / 5.9 x 3.1 x 1.5"

Weight 170 g / 6 oz

Technical Data Vibration Sensor

Resonance frequency 24 kHz
Transverse sensitivity $\leq 5\%$

Destruction limit 5000 g (peak)

Operating and storage temperature -55 ... +150 °C / -67 ... 302 °F

Housing material stainless steel

Mounting thread 1/4 - 28"

Dimensions Ø 17 x 46 mm / 0.67 x 1.8"

Weight (without cable) 52 g / 1.8 oz

More information

Manual



More product info



Similar products

