



PCE Americas Inc.
711 Commerce Way
Suite 8
Jupiter
FL-33458
USA
From outside US: +1
Tel: (561) 320-9162
Fax: (561) 320-9176
info@pce-americas.com

PCE Instruments UK Ltd.
Units 12/13
Southpoint Business Park
Ensign way
Hampshire / Southampton
United Kingdom, SO31 4RF
From outside UK: +44
Tel: (0) 2380 98703 0
Fax: (0) 2380 98703 9
info@pce-instruments.com

www.pce-instruments.com/english
www.pce-instruments.com

Technical Infrared Thermometer PCE-780

Digital infrared thermometer scanner for the display of temperature, humidity and dew point temperature / Optical alarm / Backlight / Automatic shutdown

The PCE-780 consists of an infrared thermometer and an integrated humidity meter. With the two sensors, it can record values to determine the dew point. If this dew point is reached or undershot, there is a risk of moisture settling and mold growing. The dew point, which is calculated by the PCE-780, is displayed on the high-contrast LCD display. The control buttons can be used to set alarm values. If the surface temperatures are exceeded or undercut, the PCE-780 emits a warning tone and displays either a LOW or a HIGH alarm.

The PCE-780 also has a relative value measuring function. Thus, in the structural analysis, a temperature can be stored as a reference in the instrument by a measuring point. If further measurements are subsequently carried out, a good / bad evaluation by the PCE-780 is carried out via a colored bar graph. Furthermore, the PCE-780 offers the possibility to determine the maximum, minimum and average value of the infrared temperature.

- Infrared temperature measurement
- Air temperature and humidity measurement
- Calculation of dew point
- High contrast LCD display
- Adjustable high and low alarm
- Max, Min, Average measurement
- External temperature sensor can be connected
- Adjustable degree of emission

Technical specifications:

Measuring range

Infrared: -76... 932°F / -60 ... 500°C

Type K thermocouple: -83... 2552°F / -64... 1400° C

Air temperature: -4... 149°F / -20... 65°C

Wet bulb temperature: -4... 149°F / -20... 65°C

	Dew point: -58... 122°F / -50... 50°C
	Humidity: 1... 99% rh
Accuracy (at 68... 78°F / 20... 26 ° C ambient temperature)	Infrared 59... 95°F / 15... 35 °C: ± 33°F / 1.0°C -22... 932°F / -33... 500°C: ± 2% of Mw. or ± 35°F / 2°C Thermocouple type K ± 1% of Mw. or ± 33°F / 1°C Air temperature: ± 36.5°F / 2.5°C Wet bulb temperature: ± 36.5°F / 2.5°C Dew point 20... 30% RH: ± 36.5°F / 2.5°C 31... 40% RH: ± 35°F / 2°C 41... 95% RH: 34.7°F / 1.5°C Air humidity: 20... 80%: ± 3% Balance: ± 5% 32.2°F / 0.1 °C 33°F / 1 °C
Resolution	
Emissivity	0.1 ... 1
Response time	1 second
Optical resolution	12: 1
Power supply	2 x 1.5V AA battery
Battery life (without laser & display lighting)	Approx. 180 minutes Approx. 140 minutes (continuous operation)
Weight	< 1 lb / 240 g
Dimensions	1.8 x 5.6 x 7.3 in / 46 x 143 x 184.8 mm

Delivery contents:

- 1 x PCE-780 digital infrared thermometer
- 1 x Type K thermocouple
- 2 x 1.5 V AAA batteries
- 1 x User manual