

# HIH-5030/5031 Series Low Voltage Humidity Sensors

#### DESCRIPTION

The HIH-5030/5031 Series Low Voltage Humidity Sensors operate down to 2.7 Vdc, often ideal in battery-powered systems where the supply is a nominal 3 Vdc.

The HIH 5030/5031 complements our existing line of 5 Vdc SMD (Surface Mount Device) humidity sensors. SMD packaging on tape and reel allows for use in high volume, automated pick and place manufacturing, eliminating lead misalignment to printed circuit board through-holes.

The HIH-5030/5031 Series Humidity Sensors are designed specifically for high volume OEM (Original Equipment Manufacturer) users.

Direct input to a controller or other device is made possible by this sensor's near linear voltage output. With a typical current draw of only 200  $\mu$ A, the HIH-5030/5031 Series is ideally suited for many low drain, battery operated systems.

Tight sensor interchangeability reduces or eliminates OEM production calibration costs.

#### **FEATURES**

- Operates down to 2.7 Vdc, often ideal in battery-powered systems where the supply is a nominal 3 Vdc.
- Tape and reel packaging allows for use in high volume pick and place manufacturing (1,000 units per tape and reel)
- Molded thermoset plastic housing
- Near linear voltage output vs %RH
- Laser trimmed interchangeability
- Low power design
- Enhanced accuracy
- Fast response time
- Stable, low drift performance
- Chemically resistant

The HIH-5030/5031 Series delivers instrumentation-quality RH (Relative Humidity) sensing performance in a competitively priced, solderable SMD.

The HIH-5030 is a covered integrated circuit humidity sensor. The HIH-5031 is a covered, condensation-resistant, integrated circuit humidity sensor that is factory-fitted with a hydrophobic filter allowing it to be used in many condensing environments including industrial, medical and commercial applications.

The RH sensor uses a laser trimmed, thermoset polymer capacitive sensing element with on-chip integrated signal conditioning.

The sensing element's multilayer construction provides excellent resistance to most application hazards such as condensation, dust, dirt, oils and common environmental chemicals.

Sample packs are available. See order guide.

#### POTENTIAL APPLICATIONS

### Industrial

- Air compressors
- Battery-powered systems
- Drying equipment
- HVAC (includes air conditioning, air movement, thermostats, humidifiers, de-humidifiers, humidistats, enthalpy sensing)
- OEM assemblies
- Office automation equipment
- Process equipment
- Refrigeration (includes bulk and transport systems)
- Telecommunications cabinets
- Weather stations and meteorology equipment

#### Medical

- Hospital air compressors
- Infant incubators
- Microenvironments
- Sleep apnea equipment
- Treadmill stress monitoring equipment

# HIH-5030/5031 Series

### Table 1. Performance Specifications (At 3.3 Vdc supply and 25 °C [77 °F] unless otherwise noted.)

Parameter	Minimum	Typical	Maximum	Unit	Specific Note
Interchangeability (first order curve)					
0% RH to 10% RH, 90% RH to 100% RH	-7	_	7	% RH	_
11% RH to 89% RH	-3	_	3	% RH	
Accuracy (best fit straight line) 11% RH to 89% RH	-3	_	+3	% RH	4
Hysteresis	_	2	_	% RH	-
Repeatability	_	±0.5	_	% RH	-
Settling time	—	_	70	ms	-
Response time (1/e in slow moving air)	_	5	_	S	-
Stability (at 50% RH in 5 years)	—	±1.2	_	% RH	1
Voltage supply	2.7	_	5.5	Vdc	2
Current supply	_	200	500	μA	-
Voltage output (1st order curve fit)	V <sub>OUT</sub> =(V <sub>SUPPLY</sub> )(0.00636(sensor RH) + 0.1515), typical at 25 °C				
Temperature compensation	Tru	ie RH = (Sensor	<sup>r</sup> RH)/(1.0546 -	– 0.00216T), T ir	ר °C
Output voltage temp. coefficient at 50% RH, 3.3 V	_	-2	_	mV/°C	-
Operating temperature	-40[-40]	See Figure 2.	85[185]	°C[°F]	-
Operating humidity (HIH-5030)	0	See Figure 2.	100	% RH	3
Operating humidity (HIH-5031)	0	See Figure 2.	100	% RH	_
Storage temperature	-50[-58]	_	125[257]	°C [°F]	
Storage humidity		See Figure 3.		% RH	3

### **Specific Notes:**

1. Includes stress outside of recommended operating zone.

2. Device is tested at 3.3 Vdc and 25  $^\circ\text{C}.$ 

- 3. Non-condensing environment. When liquid water falls on
- the humidity sensor die, output goes to a low rail condition indicating no humidity.
- 4. Total accuracy including interchangeability is  $\pm 3$  %RH.


### **General Notes:**

• Sensor is ratiometric to supply voltage.

- Extended exposure to ≥90 % RH causes a reversible shift of 3 % RH.
- Sensor is light sensitive. For best performance, shield sensor from bright light.




### Low Voltage Humidity Sensors



### Figure 1. Operating Environment (Non-condensing environment for HIH-5030 catalog listings only.)





### HIH-5030/5031 Series





Figure 3. Typical Output Voltage vs Relative Humidity (At 25 °C and 3.3 Vdc.)





### Low Voltage Humidity Sensors





Figure 6. HIH-5030 PCB Landing Pattern (For reference only. mm/[in])



### HIH-5030/5031 Series






Figure 7. HIH-5031 Mounting Dimensions (For reference only. mm/[in])

Figure 8. HIH-5031 PCB Landing Pattern (For reference only. mm/[in])




### Low Voltage Humidity Sensors



### Figure 9. Tape and Reel Dimensions (For reference only. mm/[in])

### Figure 10. Typical Application Circuit



#### **ORDER GUIDE**

Catalog Listing	Description
HIH-5030-001	Covered integrated circuit humidity sensor, SMD, 1000 units on tape and reel
HIH-5031-001	Covered, filtered integrated circuit humidity sensor, SMD, 1000 units on tape and reel
HIH-5030-001S	Sample pack: covered integrated circuit humidity sensor, SMD, five units on tape
HIH-5031-001S	Sample pack: covered, filtered integrated circuit humidity sensor, SMD, sample pack, five units on tape

### ADDITIONAL HUMIDITY SENSOR INFORMATION

See the following associated literature is available on the Web:

- Product installation instructions
- Application sheets:
  - Humidity Sensor Performance Characteristics
  - Humidity Sensor Theory and Behavior
  - Humidity Sensor Moisture and Psychrometrics
  - Thermoset Polymer-based Capacitive Sensors

### 

### MISUSE OF DOCUMENTATION

- The information presented in this product sheet is for reference only. Do not use this document as a product installation guide.
- Complete installation, operation, and maintenance information is provided in the instructions supplied with each product.

Failure to comply with these instructions could result in death or serious injury.

### WARRANTY/REMEDY

Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship. Honeywell's standard product warranty applies unless agreed to otherwise by Honeywell in writing; please refer to your order acknowledgement or consult your local sales office for specific warranty details. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace, at its option, without charge those items it finds defective. The foregoing is buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose. In no event shall Honeywell be liable for consequential, special, or indirect damages.

While we provide application assistance personally, through our literature and the Honeywell web site, it is up to the customer to determine the suitability of the product in the application.

Specifications may change without notice. The information we supply is believed to be accurate and reliable as of this printing. However, we assume no responsibility for its use.

### A WARNING

### PERSONAL INJURY

DO NOT USE these products as safety or emergency stop devices or in any other application where failure of the product could result in personal injury.

Failure to comply with these instructions could result in death or serious injury.

### SALES AND SERVICE

Honeywell serves its customers through a worldwide network of sales offices, representatives and distributors. For application assistance, current specifications, pricing or name of the nearest Authorized Distributor, contact your local sales office or:

E-mail: info.sc@honeywell.com

Internet: www.honeywell.com/sensing

### Phone and Fax:

Asia Pacific	+65 6355-2828
	+65 6445-3033 Fax
Europe	+44 (0) 1698 481481
	+44 (0) 1698 481676 Fax
Latin America	+1-305-805-8188
	+1-305-883-8257 Fax
USA/Canada	+1-800-537-6945
	+1-815-235-6847
	+1-815-235-6545 Fax

Sensing and Control Honeywell 1985 Douglas Drive North Golden Valley, MN 55422 www.honeywell.com

## Honeywell

009050-2-EN IL50 GLO Printed in USA Mar 2010 © 2010 Honeywell International Inc. All rights reserved.