

## This document was generated on 06/27/2011

## PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: Status: Description:

0640000072 Active

Hand Tool Repair Kit

Documents:

RoHS Certificate of Compliance (PDF)

General

Product Family Series Comments

Function Geographic Area Level of Automation More Detailed Tech Information Product Name Survey Tool Type Application Tooling <u>T0103</u> 0192930034 (1 pivot pin)|0192930020 (2 pivot pins, short)|0192930028 (1 handle, return spring)| 0192930027 (1 ratchet, pawl extension spring)| 0194110130 (1 nut, self locking)|0194110158 (1 roll pin)|0194110181 (2 rings, c.e.) Crimp Global Manual <u>applicationtooling@molex.com</u> N/A <u>www.molex.com//review/apptool\_survey.html</u> Repair Kit Not Reviewed REACH SVHC Not Reviewed Low-Halogen Status Not Reviewed Need more information on product environmental compliance? Email productcompliance@molex.com For a multiple part number RoHS Certificate of Compliance, click here

China RoHS

EU RoHS

**Compliance Status** 

Please visit the <u>Contact Us</u> section for any non-product compliance questions.

Search Parts in this Series T0103Series

## Material Info

This document was generated on 06/27/2011
PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION